

# How to calibrate touch screen for Win7


Note: If you use Win7 Basic, starter and RS232 (Serial type) touch screen controller, you must install our Win 7 driver which includes calibration utility. This utility works same as Win XP/2K/Vista.

## Step 1


- Once you connect USB cable of touch screen to USB port of PC
- Tray icon at the right bottom side will be shown and then "install device driver software" will be shown.
- After a few seconds "Your device is ready to use" will be shown.

## Step 2


- Go to "Control Panel". - start > Control Panel




- Select "Tablet PC Settings"



1) At "Display": If you use Multi Monitor, then you must select your display system integrated with touch screen. If you use only one display system, you don't have to select. (Default select is 1.)



2) Calibrate...: click to run calibration utility.



And start to touch the black cross line to calibrate as blow picture.



Finish Calibration.

If you see any problem on accuracy or something, please contact us.